



PHOTO 1 – View of the 112 and 114 Brent Street MSL properties looking from the southeast. Photo was taken prior to the installation of the protective liner.



PHOTO 2 – Workers completing the installation of the LDPE protective liner at 114 Brent Street. Photo was taken looking north to south.





PHOTO 3 – Schnabel Engineering personnel laying out the X-Y survey grid for the geophysical study. Photo was taken looking east to west on the 114 Brent Street MSL property.



PHOTO 4 – View of the Schnabel Engineering project manager gathering data for the electromagnetic (EM) study portion of the geophysical survey. The EM study was conducted to identify areas containing metallic debris.