




**KUHLMAN ELECTRIC CORPORATION
PLANT SITE REMEDIATION REPORT**

**Kuhlman Electric Corporation
Crystal Springs, Mississippi**



Prepared for


BorgWarner Inc.

June 2004



KUHLMAN ELECTRIC CORPORATION PLANT SITE REMEDIATION REPORT

**Kuhlman Electric Corporation
Crystal Springs, Mississippi**



Prepared for
BorgWarner Inc.

Prepared by
MARTIN & SLAGLE GEOENVIRONMENTAL ASSOCIATES, LLC
208A SUTTON AVE.
PO Box 1023
BLACK MOUNTAIN, NC 28711

June 2004

Robert L. Martin, L.G.
Principal Geologist

Christine Slagle
Principal Scientist

TABLE OF CONTENTS

Kuhlman Electric Corporation Crystal Springs, Mississippi Plant Site Remediation Report

1.0	Executive Summary	1-1
2.0	Introduction	2-1
2.1	Background	2-1
2.2	Site Description	2-2
2.3	Previous Investigations	2-2
3.0	Remediation Activities	3-1
3.1	Excavation and Disposal	3-2
3.1.1	Impacted Soil	
3.1.2	Stockpiles	
3.1.3	Tree Root Washing	
3.1.4	Concrete and Asphalt	
3.1.5	Water Disposal	
3.2	Backfilling	3-7
3.3	Engineered Cap	3-8
3.4	Additional Assessment Sampling	3-9
4.0	Confirmation Sampling Program	4-1
5.0	Analytical Program and QA/QC	5-1
5.1	Sampling Objectives	5-1
5.2	Analytical Methods	5-1
5.3	Key Personnel	5-2
5.4	Quality Assurance Objectives for Data	5-3
5.5	Sample Control and Field Records	5-4
5.5.1	Sample Identification	
5.5.2	Chain of Custody Procedures	
5.5.3	Field Records	
5.6	Laboratory QA/QC	5-5
5.7	Data Review and Validation	5-6
5.8	Air Monitoring	5-6