

**FILE COPY**

# TRIANGLE LAB

## Analytical Results For Kuhlman Electric Corporation Crystal Springs, Mississippi

July 15, 2002 Report

BOOK I

Project # 57752A

**Summary Table of Contents**  
**Soil Dioxin/Furan Analytical Laboratory Data Sheets**  
**Crystal Springs Site, Mississippi**

Sample Location	Depth (ft)	Book No.
TR-1	0-0.5	I
TR-1	0.5-1	I
TR-2	0-0.5	I, II
TR-2	0.5-1	I, II
DP-3	0.5	III
DP-3	0.5-1.0	I, II
TR-3	0-0.5	I, II
TR-3	0.5-1	II
DP-27	0.5	III
DP-27	0-2	VI
DP-39	0.5	III
DP-39	0-2	VI
DP-65	0.5	III
DP-65	0-2	V
DP-82	0.5	IV, V
DP-82	0-2	V
DP-104	0.5	IV, V
DP-104	0-2	V
DP-112	0.5	II
DP-112	2	III
DP-126	0.5	IV, V
DP-137	0.5	III
DP-137	0-2	V
DP-143	0.5	III
DP-143	0-2	V
DP157	0-0.5	VII
DP157	0.5-1	VII
DP157	1.0-2.0	VII
DP159	0-0.5	VII
DP159	0.5-1	VII
DP159	1.0-2.0	VII
DP-160	0-0.5	I,II
DP-163	0-0.5	I,II
DP-163	0-2	V
DP164	0-0.5	VI
DP164	0.5-1	VI
DP164	2-Jan	VI
DP177	0-0.5	VII
DP177	0.5-1	VII
DP177	1.0-2.0	VII
DP-179	0-0.5	I,II
DP-179	0-2	V
DP-209	0-0.5	IV, V
DP-209	0-2	VI
DP-210	0-0.5	I, II
DP220	0-0.5	VI
DP220	0.5-1	VI

**Summary Table of Contents**  
**Soil Dioxin/Furan Analytical Laboratory Data Sheets**  
**Crystal Springs Site, Mississippi**

<b>Sample Location</b>	<b>Depth (ft)</b>	<b>Book No.</b>
DP220	1.0-2.0	VI
DP-642	0-0.5	IV, V
DP-642	0-2	VI
DP-643	0-0.5	II
DP-655	0-0.5	II
DP-675	0-0.5	IV
DP-676	0-0.5	VI, V
DP-676	0-2	VI
DP-692	0-0.5	IV, V
DP-695	0-0.5	IV
DP-702	1.5-2	I, II