

Kuhlman Cleanup News

Newsletter on Kuhlman Environmental Cleanup in Crystal Springs, MS

SOIL VAPOR EXTRACTION SYSTEM UPDATE

The Soil Vapor Extraction System has been in operation at the plant for over 18 months. Ongoing testing indicates that the system has continued to achieve its intended purpose throughout this period and is safely removing chemicals from the soil beneath the plant. Sampling within the KEC facility will continue to be performed regularly.

MONITOR WELL MODIFICATIONS

In cooperation with the City of Crystal Springs, KEC is making changes to the protective covers on some of the monitoring wells within or near areas of the streets that are scheduled for paving. These modifications will ensure that the wells are adequately protected and the new covers will match the paving levels to avoid any “bumps” in the newly surfaced streets. This work is being performed just ahead of the paving contractor’s work and markers are in place now that will be removed once the paving is completed. Pictures have been included on the back.

WATER MONITORING

The semi-annual sampling of the groundwater monitoring wells was performed in March and a report will be provided to MDEQ soon.

UPCOMING EVENTS

- Groundwater Monitoring Event Reporting.
- Operation of the full scale Soil Vapor Extraction system.
- Continued monitoring of existing public supply wells.
- Analytical tests for the second water supply well.

PUBLIC DOCUMENTS REPOSITORY

Public documents referenced in the Newsletter are available at:

- Crystal Springs Library; and
- www.mdeq.state.ms.us.

QUESTIONS OR COMMENTS

Please submit questions or comments to Brenda Bell Caffee of Caffee, Caffee and Associates at 601-336-7212.

REPLACEMENT COVERS FOR MONITORING WELLS

